
CONTENTS

VOLUME I

Preface *xxi*

Acknowledgements *xxix*

Glossary of Terms and Acronyms *xxxv*

PART ONE *INTRODUCTION*

1 Introduction 3

PART TWO *FACTS SURROUNDING THE CRASH OF FLIGHT 1363*

2 Air Ontario Flights 1362 and 1363 15

3 Dryden Municipal Airport and Air Ontario Facilities,
March 10, 1989 22

4 Meteorological Information 28

5 Events and Circumstances at the Dryden Municipal Airport
Preceding Takeoff 49

6 Circumstances Related to the Takeoff and Crash of Flight 1363 79

7 The Crash and the Response 93

8 Dryden Area Response 101

PART THREE CRASH, FIRE-FIGHTING, AND RESCUE SERVICES

- 9 Dryden Municipal Airport Crash, Fire-fighting, and Rescue Services 135**

PART FOUR AIRCRAFT INVESTIGATION PROCESS AND ANALYSIS

- 10 Technical Investigation 219**
- 11 Aircraft Crash Survivability 275**
- 12 Fokker F-28, Mk1000, Aircraft Performance and Flight Dynamics 301**

VOLUME II

PART FIVE THE AIR CARRIER – AIR ONTARIO INC.

- 13 Corporate History 389**
- Austin Airways Limited 389
- Air Ontario Limited 394
- Austin Airways and Air Ontario Limited: Pre-Merger 395
- The Merger into Air Ontario Inc. 398
- Change in Ownership: January 1987 398
- Merging Austin Airways and Air Ontario Limited 399
- Air Ontario Inc. 402
- 14 Management Organization 408**
- Management Structure 408
- Operational Management: Flight Operations and Maintenance 414
- Regulatory Requirements 414
- Air Ontario Flight Operations Management 416
- Flight Operations: Summary of Structural Changes 416
- Personnel Changes 417
- Director of Flight Operations Captain Robert Nyman 417
- Vice-President of Flight Operations Peter Hill 420
- Vice-President of Flight Operations James Morrison 421
- Director of Flight Operations Clifford Sykes 422
- Vice-President of Operations Bruce Deluce 423
- Changes in the Flight Operations Department 424

- Maintenance and Engineering Management 426
 Management Selection 428
 The Selection Process 428
 The Appointment of Bruce Deluce as Vice-President of
 Operations 431
- 15 The F-28 Program: Planning 436**
- Introduction 436
 Planning the F-28 Program 439
 Fleet Rationalization 439
 Selecting the F-28 440
 Marketing Considerations 443
 Approval of the Plan 445
 The F-28 Project Plan 447
 F-28 Project Team 449
 The Role of Transport Canada: Amending Air Ontario's Operating
 Certificate 451
 Air Canada and the F-28 Program Planning 454
 The Post-Accident F-28 Pilot Survey 457
- 16 The F-28 Program: The Auxiliary Power Unit, the Minimum
 Equipment List, and the Dilemma Facing the Crew of Flight
 1363 459**
- The APU 459
 Description 459
 Engine Starts 460
 Auxiliary Electrical Power: Anti-Skid System 460
 Fire Protection: Fire Detection versus Fire Extinguishing 463
 Fire-Protection System Test 463
 Significance of an Unserviceable APU for Flight 1363 464
 Events Leading up to the Unserviceability of the APU 465
 March 5 to 9, 1989 465
 The Events of March 9, 1989 471
 Events Following the Departure of C-FONF from Toronto 474
 The Role of SOC 476
 Events of March 10, 1989 478
 Events at Thunder Bay 480
 The MEL: Use and Approval 481
 The Role of Maintenance in the Commercial Air Transportation
 System 481
 Unscheduled Maintenance: Defect Rectification and Maintenance
 Deferral 483
 Description 484
 Using the Air Ontario F-28 MEL 486

- Deferring the Repair of the APU 488
- Findings 493
- MEL Approval 493
 - The Role of the Regulator in Approving the MEL 494
 - Transport Canada's MEL Approval Policy: Recent Developments 499
 - Air Ontario's Role in the Preparation and Approval of the MEL 500
 - Findings 503
 - An Alternative Approach: Air Canada Procedures 504
 - Air Canada Practice: Operating with an Unserviceable APU 504
 - Air Canada Practice: Operating without an Approved MEL 504
 - MEL Approval and Use: Governing Legislation 506
 - Operating without an Approved MEL 510
 - Findings 522
 - Recommendations 527
- 17 The F-28 Program: Lack of Ground-Start Facilities at Dryden 529**
 - Findings 533
 - Recommendations 533
- 18 The F-28 Program: Spare Parts 534**
 - Governing Legislation 534
 - Serviceability Difficulties 535
 - Plan to Provide Spares 536
 - THY Spares Package 537
 - Parts Situation as F-28 Entered Revenue Service 541
 - Ongoing Spares Provisioning 544
 - Spare Parts: How Much Is Enough? 549
 - Findings 551
 - Recommendations 552
- 19 The F-28 Program: Flight Operations Manuals 553**
 - Terminology 553
 - Manuals in Use on C-FONF on March 10, 1989 554
 - Flight Operations Manual 555
 - Aircraft Flight Manual 564
 - Aircraft Operating Manual 564
 - Flight Attendant Manual 577
 - Legislative Requirements 580
 - Findings 583
 - Recommendations 586
- 20 The F-28 Program: Flight Operations Training 588**
 - Terminology and Regulatory Requirements 588

Flight Crew Training	591
F-28 Ground School Training	591
Aircraft Contamination	592
Cold-Soaking Phenomenon	597
Runway Contamination	600
F-28 Aircraft Flight Training	605
Captain George Morwood	605
First Officer Keith Mills	606
Aircraft Flight Simulators	606
F-28 Line Indoctrination Training	609
Company Check Pilot	609
Air Ontario's Need for Company Check Pilots	610
The Role of Captain Castonguay	613
Deficiencies Identified by Captain Castonguay	615
Captain Castonguay's Recommendations	617
Cockpit and Crew Resource Management Training	618
Cabin Attendant Training	622
Initial Training: Flight Attendant Hartwick	623
Recurrent Training: Flight Attendant Hartwick	624
Practical Training: Flight Attendant Hartwick	624
Flight Attendant Licensing: CUPE Proposal	627
Ground-Handling Personnel Training	627
Regulatory Requirements and Guidelines	627
Dryden Flight Centre Training	628
Aircraft Fuelling: Training	633
Findings	633
Recommendations	638
21 The F-28 Program: Operational Practices – Hot Refuelling and Aircraft Ground De-icing	640
Hot Refuelling	640
Air Ontario Policy	641
Air Canada Policy	647
Findings	648
Aircraft Ground De-icing	650
The Clean Aircraft Concept: Interim Recommendation No. 2	650
Air Ontario's Policy on Flights in Icing Conditions	651
Winter Operations Advisories	654
Air Ontario Memorandum on F-28 De-ice/Anti-ice Instructions	655
De-Icing of Aircraft Nearer to Runway End: Interim Recommendations – Second Interim Report	659
National Resource Specialist – Aircraft Ground De-Icing/Anti-Icing	660
Findings	660

Recommendations 663

Hot Refuelling 663

Aircraft Ground De-icing 663

22 The F-28 Program: Flight Attendant Shoulder Harness 665

The Forward Flight Attendant Station of C-FONF 667

Governing Legislation 670

Design and Manufacturing Criteria 670

United States Operational Standards 672

Application of Standards to New Aircraft 672

Application of New Standards to Existing Aircraft 672

New Seat, Safety Belt, and Shoulder Harness Requirements
(1980) 673

The Canadian Approach to the Shoulder Harness Issue 673

Amending the Aircraft Seats, Safety Belts, and Safety Harnesses
Order 675

The Role of ATAC 675

The Role of Air Ontario 678

Findings 683

Recommendations 686

23 Operational Control 687

The Purpose of Operational Control 687

Operational Control and Operations Control 688

Operational Control: Governing Legislation 689

Approved Flight Watch System 690

Operational Flight Plan 690

Qualifications for Persons Exercising Operational Control 691

The Operating Certificate 692

Pilot Self-Dispatch System versus Full Co-authority Dispatch System 694

Air Ontario's Hybrid Dispatch System 695

Co-authority Dispatch System: Classification Proposal 696

Dispatcher Training 697

Dispatcher Training at Air Ontario 697

Air Canada's Dispatcher Training 701

Operational Flight Plan: Flight Release 703

Ability of Air Canada To Provide Flight Dispatch Expertise to Air
Ontario 710

The Flight Release Requirement 710

Reliance of Air Ontario Pilots on Flight Releases 711

The Flight Release for Flight 1362/1363, March 10, 1989 713

Deteriorating Dryden Weather and Air Ontario SOC 717

Overfly Options 721

Captain Morwood and the Flight Release 722

The Thunder Bay Station Stop: Passengers versus Fuel 724
 The Performance of Air Ontario SOC: Conclusions 728
 Licensing and Training of Dispatchers 732
 Report of the Dubin Commission of Inquiry on Aviation Safety 733
 CALDA's Application for Licensing of Dispatchers 733
 ICAO and Licensing of Dispatchers 735
 Canadian Position 735
 Licensing and Labour Relations 736
 CALPA Position 737
 United States Licensed Dispatchers and FAR Provisions 737
 Findings 738
 Recommendations 741

24 Flight Safety 744

Introduction 744
 Legislative Requirements 747
 Air Ontario's Flight Safety Organization 749
 Background 749
 The Development of Air Ontario's Flight Safety Organization 753
 Three Case Studies in the Effectiveness of Air Ontario's Flight Safety
 Organization 758
 Incident No. 1: November 20, 1986 – HS-748 – Kingston,
 Ontario 758
 Incident No. 2: December 15, 1987 – HS-748 – Toronto, Ontario 760
 Incident No. 3: April 4, 1989 – F-28 – Toronto, Ontario 768
 Captain Ronald Stewart's Post-Accident Survey of F-28 Pilots 771
 Air Canada's Flight Safety Organization, and Its Involvement with Air
 Ontario 777
 Background 777
 Categorization of Aviation Occurrences at Air Canada 778
 Air Canada Internal Incident-Reporting Procedures 780
 Flight Safety: Relationship between Air Carrier and Regulator 781
 Air Canada's Assistance to Air Ontario 782
 Air Canada's Operational Review of Air Ontario (Autumn 1989) 784
 General Conclusions 785
 Findings 786
 Recommendations 788

25 Management Performance 790

Certification 792
 Approval of the Air Ontario F-28 Program 794
 The Planning and Implementation of the F-28 Program 796
 The Performance of Captain Joseph Deluce, F-28 Project Manager and
 Chief Pilot 800

The Role of Senior Flight Operations Managers	802
Air Ontario Management Selection: "Best Man for the Job"	805
Regulatory Requirements	809
Findings	813
Transport Canada's Review of the Air Ontario F-28 Program	813
Air Ontario Management Supervision of the F-28 Program	814
Recommendations	816
26 The Role of Air Canada: Parent/Subsidiary Implications	818
The Coming of Deregulation	820
The Regulated versus the Deregulated Aviation Industry	821
The Impact of Deregulation	824
Control of the Feed	826
Minority versus Majority Equity Interest	830
Implications of Common Employment	831
The Commercial Relationship	835
Common Livery	836
Interiors	836
Use of Air Canada's AC Designator	836
Standards of Service	837
Timetables	837
Computer Services	837
Telephone Answering	838
Ticketing	838
Ground-Handling	838
Aircraft Services	838
Advertising	839
Aeroplan	839
The Operational Relationship	841
Auxiliary Power Unit	842
The Introduction of Jet Service	843
Minimum Equipment List	843
Manuals	844
Aircraft Defects (Snags)	845
Refuelling	845
De-icing	846
Operational Control and Flight Planning: Air Canada versus Air Ontario	847
Dispatcher Training	849
Flight Safety Overview	850
Operational Review	850
Flight Safety Organization	852
Parent-Feeder Operational Standards	852
Conclusions	853

VOLUME III

PART SIX *TRANSPORT CANADA*

- 27 Organization 857
- 28 Conditions at Transport Canada in the Early 1980s 867
- 29 Economic Deregulation and Deficit Reduction 870
- 30 The Effects of Deregulation and Downsizing on Aviation Safety 881
- 31 Aviation Regulation: Resourcing Process 916
- 32 Audit Program 944
- 33 Audit of Air Ontario Inc., 1988 953
- 34 Operating Rules and Legislation 1000
- 35 Company Check Pilot 1015
- 36 Contracting Out, Waivers, and Spot Checks 1023
- 37 Safety Management and the Transport Canada Organization 1030

PART SEVEN *HUMAN FACTORS*

- 38 Crew Information 1055
- 39 Crew Coordination and the Communication of Safety Concerns by Passengers 1071
- 40 Human Performance: A System Analysis 1096

PART EIGHT *LEGAL AND OTHER ISSUES BEFORE THE COMMISSION*

- 41 The Aviation Accident Investigation Process in Canada 1143

- 42 **Aviation Incident and Occurrence Reporting and the Issue of Pilot Confidentiality** 1165
- 43 **Objection to Production of Documents, Based on a Confidence of the Queen's Privy Council, Section 39, Canada Evidence Act, R.S.C. 1985, c.C-5** 1187
- 44 **Inquiries Act, R.S.C. 1985, c.I-11, Section 13** 1192

PART NINE CONSOLIDATED RECOMMENDATIONS

- Interim Report, 1989* 1203
- Second Interim Report, 1990* 1204
- Final Report* 1208

GENERAL APPENDICES

- A Order in Council 1247
- B Counsel and Representatives for Parties with Standing 1250
- C Parties Granted Full, Limited, and Special Participant Status and Observer Status 1253
- D Witnesses Appearing before the Inquiry 1254
- E Inquiry Schedule 1275
- F Letter from the Chief Coroner for Ontario, July 15, 1991 1277
- G Time Sequence of Events Surrounding the Crash 1280
- H Summary of Fatalities and Survivor Injuries 1294
- I Minutes of Debriefing Meetings, Town of Dryden, March 13 and 16, 1989 1301
- J U.S. Department of Transportation, Federal Aviation Administration, Advisory Circular 120-51, Cockpit Resource Management Training, Dated December 1, 1989 1319
- K Transport Canada Response to the Interim Recommendations of the Second Interim Report, Dryden Commission of Inquiry 1327
- L Letter of Notice Sent by Commission Counsel to Affected Parties, re: Inquiries Act, R.S.C. 1985, c.I-11, Section 13 1334
- M Rulings 1337